

IODP EXP 358 Daily Geomechanics Report

Report #036 20181215

RTG Team

RTG Supervisor(s)	David Castillo / Thomas Finkbeiner / Demian Saffer
RTG Watch Lead (00:00-12:00)	Emily Wisbey
RTG Watch Lead (12:00-24:00)	Toby Colson

Well Status

Site Name:	C0002	Hole Name:	Q
Water Depth:	1,939.0 m	RT-MSL:	28.5 m
Current Depth:	No bit in hole mBRT (mTVD)	Section TD:	5,667.5 mBRT (5,664.5) (mTVD)
Section #:	1	CSG Depth/Size:	(4855.0) 11-3/4 mBRT
Static MW:	1.37 sg	Current ECD:	1.41 sg
FIT/LOT/ XLOT:	FIT maximum pressure = 1.45 sg, Possible "LOP" = 1.43 sg @4855 mBRT		
Current formation/ lithology:	Shale		
Sensor Offsets from the Bit:	N/A		
Other BHA Offsets from the Bit	N/A		
Current Operations:	Rigged up wireline. Made up 11-3/4" EZSV to plug setting tool and RIH on wireline to setting depth. Commenced depth correlation.		

Geomechanics Alert

GREEN	<p>Green = Projected model remains accurate</p> <p>White = Unanticipated deviation from model which <i>should not</i> affect drilling</p> <p>Yellow = Unanticipated deviation from model which <i>may</i> affect drilling</p> <p>Red = Imminent requirement to stop drilling</p>
Basis for Alert Level + Recommendations	<p>No further observations have been made to suggest any change in wellbore condition.</p> <p>1.37 sg remains recommended MW for Section 1.</p>

Principal Findings


N/A.

IODP EXP 358 Daily Geomechanics Report

Report #036 20181215

Observations Summary

Use this space to discuss any observations while drilling, running casing etc.

Fracture Gradient	N/A
Pore Pressure	No significant gas peaks or other indications of overpressure observed.
Wellbore Breakout	N/A
Tensile Failure	N/A
Drilling Parameters	N/A
Other	<p>Based on AFR image collected in C2P hole (Figure 1), a comparison between bedding at the window setting depths indicate C2Q would have encountered beds dipping $\sim 85^\circ$ to the NNW, while the C2R planned window is likely to encounter beds dipping 60°-70° to the NNW.</p> <ul style="list-style-type: none"> – Both bedding plane geometries are vulnerable to anisotropic bedding plane failure. – Both window setting depths likely experienced anisotropic failure during Exp 348 due to inadequate MW and mechanically-induced hole damage from numerous pack-off events. It is unlikely the hole is in pristine condition and may contain cement in the annulus with clasts of well-rounded blocky cavings from Exp 348. – The cement at the C2R window may or may not have been damaged during C2Q operations. <p>Note: High-resolution repeat passes of the AFR image tool did not occur across the two window depths; however, repeat passes below the window depths indicated substantial anisotropic failure. We would expect similar failure at the window depths since bedding planes are suitable for failure and they experienced pack-off events.</p>  <p style="text-align: center;">Figure 1 Proposed C002Q v Actual C002P whipstock setting depths *Windows represented by grey circles on depth track</p>

Analysis

Drilling Experience Analysis

N/A

Cuttings Analysis

N/A

Cavings Analysis

N/A

LWD Data Analysis

N/A

SFIB Analysis

N/A

IODP EXP 358 Daily Geomechanics Report

Report #036 20181215

Geomechanical Model Review

No change in the latest stress model.

