

Chikyū DAILY MORNING REPORT

Mission No. : CK18-01 Exp. No. 380

Report No. : 18

Site Name : C0006 Hole Name : C0006G Lat. 33° 01.6388'N Long. 136°47.6463'E Report Date : 30/Jan/2018
 Depth : @24:00 4,395.0 mBRT 495.0 mbsf Progress : 0.0 m Seabed Depth : 3,900.00 mBRT RT-MSL : 28.5 m
 Depth : @06:00 4,395.0 mBRT 495.0 mbsf Drilling/Coring/Jetting Hrs. : 0.00 hrs LAST CASING : 9-5/8in x 391.00 mbsf

Summary of Operation on 29-Jan : Cont. POOH to surface. Prepare LTBMS completion run. Run LTBMS completion.
 Present Operation to 06:00 on 30-Jan : Cont. Run LTBMS completion. Sensor health check.

mBRT: meter below rotary table
 mbsf: meter below sea floor

From	To	Hrs	Code	Detail of Operation
0:00	2:00	2:00	TIRP	Cont. POOH 9-5/8"Scrapper BHA to surface. MU Bull nose, Circulation sub and Float collar with 3-1/2"TBG R3 and install centralizers as per tally. Lower 2 x Spoolers to BOP cart and install air hose from rig supply. *(01:40 to 3:28)Vessel move to 3mile up current
2:00	5:30	3:30	COMPLETION	Prepares LTBMS Completion running. Arrange moonpool. Shift CGR to wellcenter and Shift RGR to AFT slightly (RGR door is closed). Slide CGR working platform. Pass Sensor cable & Flatpack through MUX cable sheave and Blue sheave with messenger rope. Arrange 1/4"tubing on RGR upper worker platform. Transfer Measurement Van (20'container) behind BOP cart.
5:30	12:30	7:00	COMPLETION	Run LTBMS Completion to 61mBRT. Install mini-screen above bull nose and connect 1/4"hydraulic tubing, and bind 1/4"hydraulic tubing to 3-1/2"TBG w/SUS band. Once PU Strainmeter w/H-frame w/soft sling onto RTS, but scientist concerns about strainmeter is choked by soft sling (Check Strainmeter: OK). PU Strainmeter to middle pipe deck w/hanging at shackle of H-frame and install protector cover. PU strainmeter w/scientist's requirement hanging point and MU same w/bolts at Flange. Install 3-1/2"x9-7/8"spring bow type centralizer at top of 3-1/2"TBG below XO sub (VAMTOP 9.2ppf Pin x Flange). Connect 1/4"hydraulic tubing to tubing from mini-screen and Strainmeter once confirm which tubings are from Strainmeter or mini-screen. MU Sensor Carrier onto Strainmeter w/XO sub (Flange x VAMTOP 9.2ppf box) and bolts. Remove 3-1/2"x9-7/8" centralizer because centralizer can rotate slightly by hand and 1/4"tubing might be damaged when adjust the string orientation. Run Strainmeter to moonpool and remove protector cover. @10:30 Find Derrick Top Pole broken and secure same due to corrosion and vibration for a long time at welding part.
12:30	15:30	3:00	COMPLETION	Install sensor cables on each sensors @Moonpool (Strainmeter, Seismometer, Tiltmeter, Thermistor) Install sensor cables to CGR cable slot for prevent pinch between CGR rollers and TBG
15:30	17:30	2:00	COMPLETION	#1 Sensor health check Confirm all sensors good (Strainmeter, Seismometer, Tiltmeter, Thermistor)
17:30	24:00	6:30	COMPLETION	Continue to run LTBMS Completion to 147mBRT, on going. Bind Sensor cables w/Tie wrap on lower worker platform and Flatpack w/SUS band on upper worker platform. Apply rubber sleeve to sensor cables when tighten SUS band over the centralizer. Adjust sensor cable orientation for attach to TBG centralizer. Install Flatpack cable for Mini screen and Strainmeter Confirm Flatpack cable #1, #2, #3 assignment and record same Apply rubber sheat above instrument carrier for cable protection Find Joint No.84 of 3-1/2"TBG tiny protrude at pin end, skip No.84 joint. Repair Joint No.84 joint with sand paper and scotch brite to flat.

Time Breakdown (00:00 - 06:00 on 30-Jan) * The data on 00:00 - 06:00 is unofficial.

From	To	Hrs	Code	Detail of Operation
0:00	0:30	0:30	COMPLETION	Continue to run LTBMS Completion to 147mBRT. Bind Sensor cables w/Tie wrap on lower worker platform and Flatpack w/SUS band on upper worker platform. Apply rubber sleeve to sensor cables when tighten SUS band over the centralizer.
0:30	2:15	1:45	COMPLETION	#2 Sensor health check @147mBRT. Confirm all sensors good (Strainmeter, Seismometer, Tiltmeter, Thermistor)
2:15	6:00	3:45	COMPLETION	Resume to run LTBMS Completion to 240mBRT (Run No.23), on going. Bind Sensor cables w/Tie wrap on lower worker platform and Flatpack w/SUS band on upper worker platform. Apply rubber sleeve to sensor cables when tighten SUS band over the centralizer. Run Joint No.84 joint above Run No.14. Terminate Thermistor cable end along 3-1/2"TBG (Run No. 21) w/Tie wrap. T2: 245.774mbsf, T1: 240.814mbsf, Thermistor end: 237.814mbsf.

Bit Record

Bit No.	Size (in)	MFR	Type	IADC Code	S.No.	Nozzles	Depth (mBRT)		Meter-age	Hrs.	WOB (kN)		rpm		Total Rev.	Dull Condition											
							From	To			Min.	Max.	Min.	Max.		Inner	Outer	Dull	Loc. G	B F	I	O.D. NO	RP BHA				
6	8.5	TIX	MS		60903-T	3 x 20	4189.0	4290.0	101.0	1.8			0	0	0.0	1	1	WT									

BHA Record

6	Scrapper	8-1/2"Bit x 9-5/8"Scrapper x XO x 6-3/4"DC (3) x XO x 8-1/2"Slab. X XO x 6-3/4"DC (3) x Jar x 6-3/4"DC (3) x XO	Hook Wt. (kN) @ 147 mBRT
---	----------	---	--------------------------

Hook Load	624
-----------	-----

BHA	100
BHA (Below Jar)	61
HPS & Traveling block	600

Mud Type	Time	Depth (mBRT)	MW	VIS	PV	YV	Gel SL (10 ³ , 10 ⁴)	WL	Cake	pH	Pf	Cl-	Sand	Oil	Solid	K+	LGS	MBC	Temp In	Temp Out	n	K
PHG	11:00	PHG	1.06	300	38	50	42 : 80			8.6									16		0.52	3.49
SWG	13:00	SWG	1.11	300	47	94	75 : 93			11.0									16		0.42	10.60
Kill Mud	14:00	KillMud	1.30	107	35	32	36 : 50			11.0									16		0.61	1.53

Geologic Information

From	To	Lithology of core
0:00	24:00	S/B Akatsuki
0:00	24:00	G/B Meijimaru #8

Personnel @24:00

CDEX	10
Scientist	15
MQJ Crew	95
MQJ (Other)	2
MWJ	15
NuStar	3
Cementing (Sch)	3
Packer (Hal)	1
Telrite	1
Trainee	4
Frankis	4
ODI	2
Total	155

Mud Pumps : 14-P-220 @ 5.00 gallon/stroke @97%

No.	Liner Size	SFM	GPM	Press. (MPa)	Ann. Vel. (m/min)
1	6				
2	6			0	0
3	6				

Mud Materials on Board @24:00hrs (unit: kg)

Item	Received	Used	Stock
Barite (Bulk) *			270,000
TEL-GEL (Bulk)			38,000
Kunggel VO (Bulk)			41,000
Caustic soda			1,225
Lime			1,020
XCD-Polymer			100
Baracor-100			0
Prehly Gel (1.06sg)			0
Defomer 30C			16
KCI			140
NaCl			0

Mud Volume (m3)

Prehly Gel (1.06sg)	50
SWG (1.11sg)	30
NaCl Brine (1.19sg)	100
Kill mud (1.30sg)	40

Safety (HSE) and other information

Incident	Last Incident	No. LTA
LTA		
HUNS cards	54	
Remarks		

Marine Information @24:00

Heave (m)	0.2
Pitch (deg)	0.2
Roll (deg)	0.2
Vessel Heading (deg)	335
Riser Tension (ton)	-
V.D. Load (ton)	12778.9
Max Draught (m)	9.00
Thruster (kW)	1,500

Weather Information

Time	Weather	Temp. (degC)		Barometer (hPa)	Wind Speed (m/s)	Dir. (deg)	Gust (m/s)	Height (m)	Wave		Current		Visibility (km)
		Air	SW						Dir. (deg)	Period (s)	Speed(knt)	Dir. (deg)	
24:00	bc	7.0	16.0	1013.1	12.4	313.0	14.0	1.5	242	5.1	0.4	242	22

Today's Schedule : Cont. Run LTBMS Completion w/attaching sensor cables & Flatpack. Install sensor cables to Swellable packer.

Reported by : N.Sakurai / T.Yokoyama

Approved by : T.Saruhashi