Recover corrosion cap; retrieve A-3 casing packer & GeniusPlug

Underream to 9-7/8" below 9-5/8" casing

Run scraper inside 9-5/8" casing

Run 3-1/2" tubing completion assembly LTBMS string

Cement and set LTBMS; release and POOH running tool