# Hole C0010A operation sequence

Recover Corrosion Cap
Retrieve A3 Casing Packer
& GeniusPlug

Underream to 9-7/8-inch
below 9-5/8-inch casing

Run Scraper
inside 9-5/8-inch casing

Run 3-1/2-inch tubing
LTBMS Completion
assembly

Cement and Set LTBMS
Completion assembly,
release and POOH
running tool

Depth in red = meters below seafloor (mbsf)