Expedition 309/312 summary, Figure F44. Abundance of secondary mineral veins in Hole 1256D. Numbers of veins are normalized to amount of recovered material per core (veins per meter) and plotted vs. depth to top of core.