IODP-MSP (Exp. 347) VISUAL SECTION UNIT DESCRIPTION

Exp.	Site	Hole	Core	Type	Section
347	63	A	4	H	2

Date	Time	Observers
05.02.14	14:25	MK/SP



Description

- black organic-rich clay (N2.5)
- laminations by color (mm scale)
- along cracks and core liner oxidized (0-27 cm, 93-110 cm)
- very well sorted
- moderately disturbed? or perhaps highly disturbed (expanded?)
- no bioturbation visible