IODP-MSP (Exp. 364) VISUAL SECTION UNIT DESCRIPTION

Exp.	Site	Hole	Core	Type	Section
364	77	A	135	R	1

Date	Time	Observers
2.11.16	10:55	MP, AR, LF, NT



sinistral shear along upper contact of Granite xenolith. (same coarse grained granite as prev.)

Dolerite as in previous section black to green with plag laths up to 1cm and up to 1cm rounded, fine-grained aggregates (?). surrounded by Halo (up to 2 cm) lighter green/gray

- Fill of fracture fizzes mildly with acid
- Fracture is along one of several sub-parallel shear faces. (highly inclined)
- one set of sub-horizontal shear faults of greater thickness (2-3mm)
- another set of highly inclined hairline shear faces.