IODP-MSP (Exp. 386) VISUAL CORE DESCRIPTION

Exp.	Site	Hole	Core	Type	Section
386	82	B	1	H	7

Date	Time	Observers
2/18	21:40	Ishizawa



[cm] | X-CT Image | Coring Distur. | Unit | Lithol. | Grain Size (si f c g c / m vf m vc p) | Samples | Sed. Struct. Trace Fossils | Bioturb. (0 6) | Sorting (p m w) | Roundn. (a r) | Colour | Description

0
- 7.5Y 4/2 clay with dense black dots
10
- 14cm silty clay
- clay disturbed laminas? or horizontal bedding?
20
- 29~29.5 silty clay
30
- clay dense black patches
40
- clay some black patches
50
- 51~51.5 vf.s
- clay dense black patches
60
- 7.5Y 6/2 white color clay
- 7.5Y 5/2 clay with black patches and dots
70
80
- silty clay
- 7.5Y 4/2 clay
90
100
- silty clay

- bioturbated boundary
- unclear boundary
- bioturbated boundary
- clear boundary
- bioturbated boundary
- clear and irregular boundary
- unclear boundary
- gradual boundary

photo

0~101 cm