

Chikyu DAILY MORNING REPORT

Mission No. : CK18-04

Exp. No. : Exp 358

Report No. : 101

Site Name C0002 Hole Name C0002R Lat. 33° 18.0507'N Long. 136° 38.2029'E Seabed Depth : 1,967.5 mBRT RT-MSL : 28.5 m Report Date : 16/Jan/2019

Table with columns: From, To, Hrs, Code, Depth(mBRT), Detail of Operation. Contains log entries for various operations like drilling, pressure testing, and rig services.

Table with columns: From, To, Hrs, Code, Depth(mBRT), Detail of Operation. Contains log entries for drilling operations and backloading activities.

Table with columns: Bit No., Size (in), MFR, Type, IADC Code, S/No., Nozzles, Depth (mBRT), Meter-age, Hrs., WOB (kN), rpm, Total Rev. (krev), ROP (m/hr), Inner, Outer, Dull, Loc., B, G, O.D., RP.

Table with columns: BHA Record @24:00, Mud Properties @24:00, Mud Pump @24:00. Contains data for bit hole assembly, mud properties, and pump performance.

Table with columns: No., Liner Size, SPM, GPM, Press. (MPa), Ann. Vel. (m/min). Contains data for liner sizes and pump rates.

Table with columns: Item, Unit, Stock, Used, Received. Contains materials stock on board.

Table with columns: No., Arrived, Time, Departed, Are., Dept. Contains personnel information.

Table with columns: Incident, Last Incident, No. LTA. Contains safety and other information.

Table with columns: Boat Name, Status, Time @Chikyu, Departed, Arrived. Contains boat information.

Table with columns: Time, Weather, Temp. (degC), Barometer, Wind, Wave, Current, Visibility. Contains weather information.

Today's Schedule: Continue to RIH 9.851" DOC assembly. Drill out casing shoe. Continue to drill down rat hole

Reported by : A. Suzuki / T.Nishiyama / N.Sakurai
Approved by : T.Saruhashi