

IODP-MSP (Exp. 364) VISUAL SECTION UNIT DESCRIPTION

Exp. 364	Site 77	Hole A	Core 169	Type R	Section 1
-------------	------------	-----------	-------------	-----------	--------------

Date 3/10/16	Time 18:57	Observers MR. XL DK
-----------------	---------------	------------------------

[cm]	Image	Unit #	Lithology	Veins and Alteration	Structures	Core Disturbance	CT	Description	
0			IMP.					Color 5Y, 6/2.	
10			Target rock					CT, dark grey	
20			Granite					Coarse grain size granite	
30								Very strong deformation & alteration	
40								Fractures are parallel.	
50								a cataclastic vein start from 0 to 24cm	
60									
70			71-73cm Xiao						Fault:
80			74-76cm Kring						22cm 22/62, 108/106 +3
90									
100									
110									
120									
130									
140									
150									
160									

0-1cm
Kring
1-2cm
Osinski

Xiao

74-76cm
Kring

22cm 22/62, 108/106 +3